

	Type	L #	Hits	Search Text	DBs
1	BRS	L1	183933	bearing.ti.	USPAT; US-PGPUB; EPO; JPO; DERWENT
2	BRS	L2	13	1 and (emitter).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
3	BRS	L3	5	2 and (receiver).clm.	USPAT; US-PGPUB; EPO; JPO; DERWENT
4	BRS	L4	4	3 and (CPU ECU computer processor microprocessor)	USPAT; US-PGPUB; EPO; JPO; DERWENT
5	BRS	L5	6833	1 and (hub)	USPAT; US-PGPUB; EPO; JPO; DERWENT
6	BRS	L6	1	2 and (flange)	USPAT; US-PGPUB; EPO; JPO; DERWENT
7	BRS	L7	2090	5 and (flange)	USPAT; US-PGPUB; EPO; JPO; DERWENT
8	BRS	L9	1	8 and (receiver)	USPAT; US-PGPUB; EPO; JPO; DERWENT
9	BRS	L10	10	"5678933"	USPAT; US-PGPUB; EPO; JPO; DERWENT
10	BRS	L11	2	10 and (emitter)	USPAT; US-PGPUB; EPO; JPO; DERWENT
11	BRS	L12	0	9 and (position displac\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
12	BRS	L13	4	10 and (position displac\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT
13	BRS	L8	4	7 and (emitter)	USPAT; US-PGPUB; EPO; JPO; DERWENT

	Time Stamp	Comments	Error Definition	Erro rs
1	2004/08/14 10:17			0
2	2004/08/14 10:18			0
3	2004/08/14 10:18			0
4	2004/08/14 10:18			0
5	2004/08/14 10:18			0
6	2004/08/14 10:18			0
7	2004/08/14 10:18			0
8	2004/08/14 10:18			0
9	2004/08/14 10:19			0
10	2004/08/14 10:19			0
11	2004/08/14 10:19			0
12	2004/08/14 10:19			0
13	2004/08/14 10:20			0